



Ref.	a	b	d1	d2	d3	d4	d5
DT 1 - 1000	263	60	M30x2	56	56	110	90
DT 1 - 2000	340	65	M42x3	70	70	125	104
DT 1 - 3150	372	70	M48x3	80	90	150	125



Ref.	Qty.	Parts	DT 1kV / 1000A - DT 2000A - DT 3150A DIN 42530
1	1	Top Porcelain (Isolierkörper-Oberteil)	A1 1000 - A1 2000 - A1 3150
2	1	Bottom Porcelain (Isolierkörper-Unterteil)	B1 1000 - B1 2000 - B1 3150
3	1	Connecting Bolt Z (Bolzen mit Anschlußstück)	Z1000 - Z2000 - Z3150 / E Cu F25
4	1	Washer E (Scheibe E)	E1000 - E2000 - E3150 / Ms58 F37
5	1	Washer G (Scheibe G)	G1000 - G2000 - G3150 / Ms58 F37
6	1	Connection Flag (Flachanschlußstück)	EP1000 - FP2000 - FP3150 / DIN43675
7	1	Ring Gasket J (Dichtring J)	J1 1000 - J1 2000 - J3 3150/ NBR *
8	1	Plain Gasket M (Flachdichtung M)	M1 1000 - M1 2000 - M1 3150 / NBR *
9	1	Plain Gasket N (Flachdichtung N)	N 1000 - N 2000 - N 3150 / NBR *
10	1	Internal Gasket X (Flachdichtung X)	X 1000 - X 2000 - X 3150/ NBR *
11	1	Internal Gasket R (Flachdichtung R)	R 1000 - R 2000 - R 3150/ NBR *
13	1	Brass Nut (Sechskantmutter)	M30x2 - M42x3 - M48x3 DIN 934 / Ms 58 F37
16	2	Hexagon Head Screw (Sechskantschraube)	/ Zinc or Inox
17	2	Washer (Spannscheibe)	/ Zinc or Inox